




भारत सरकार
केन्द्रीय लोक निर्माण विभाग

कार्यालय : सहायक अभियंता केन्द्रीय उपमण्डल झाँसी



पत्रांक 54(32)/K.V.- Babina/JCSD/GCD/2020 -21/ 353


दिनांक:- 27/05/2021

To,
The Principal,
Kendriya Vidyalaya Babina Cantt.
Jhansi (U.P.)

Subject :- Building safety certificate –Reg.

With reference to your letter No. 30112/2020-21/ K.V.B. /41 dated 19-05-2021 undersigned visited the Kendriya vidyalaya Babina cantt. along with Mr. Ramprakash Verma TGT from KV Babina cantt. on 25-05-2021 .The following observations were made in view of structural stability of the buildings constructed in the school.

- 1- Old class room ,senior secondary block , assembly ground block , primary block multipurpose hall , administrative block – these buildings were constructed in 1966 . Cracks of walls and joints ; minor cracks in beams are visible . Dampness is observed in many places throughout the building .These structures may be used after special repairs & maintenance.
- 2- Library block, Science lab block - Structure is stable, sound and safe but at few places annual repair & maintenance is required. These structures may be used after annual repairs & maintenance.
- 3- Proper drainage on the top floor with proper slope is required to protect the buildings. Hence buildings are structurally safe and may be used after special repair & maintenance.


27-05-21

सहायक अभियंता
झाँसी केन्द्रीय उपमण्डल
के.लो.नि.विभाग

प्रतिलिपि :- कार्यपालक अभियंता ग्वालियर केन्द्रीय मण्डल के0लो0नि0विभाग ,ग्वालियर को सादर सूचनार्थ प्रेषित ।

सहायक अभियंता